



NOTE: Excessive movement due to thermal expansion/contraction may cause insulation buckling and bowing. It is the Design Professional's responsibility to determine the appropriateness of this detail.



**Expansion Joint**

EPDM Systems

ACCEPTABLE SYSTEMS:  
All Systems

MAXIMUM WARRANTY: **20 Years**

ISSUE / REVISION  
DATE:  
6-24-2015

NOT TO SCALE

DETAIL NO.

**E-11.03**